

ABSTRAK

Kenyamanan visual merupakan suatu prinsip desain yang terfokus pada penciptaan lingkungan fisik yang berhubungan dengan elemen-elemen visual dalam arsitektur untuk menciptakan pengalaman positif bagi pengguna bangunan tersebut. Gedung olahraga adalah suatu tempat yang didesain untuk memwadhahi kegiatan olahraga, sudah seharusnya gedung olahraga mampu memberikan pengalaman positif bagi penggunanya sehingga dapat memberi kesan nyaman melalui visual yang ditampilkan. Dalam menilai kenyamanan visual terdapat beberapa aspek yang perlu diperhatikan yaitu tata letak, intensitas cahaya, sudut pandang penonton, dan tata warna. Penelitian ini menggunakan metode kualitatif serta kuantitatif. Penelitian ini dimulai dari melakukan pengamatan pada lokasi penelitian, setelah melakukan pengamatan kemudian dilakukan identifikasi validasi data berdasarkan SNI pada gedung olahraga. Hasil pengamatan menunjukkan masih terdapat beberapa aspek yang belum sesuai dengan SNI yang telah ditetapkan. GOR PT. Arun masih memiliki kekurangan dari segi pencahayaan dan fasilitas pengguna sehingga dapat mempengaruhi kenyamanan visual pengguna.

Kata kunci: Gedung olahraga, kenyamanan visual, SNI

ABSTRACT

Visual comfort is a design principle that focuses on creating a physical environment that relates to visual elements in architecture to create a positive experience for users of the building. Sports building is a place designed to accommodate sports activities, it should be able to provide a positive experience for its users so that it can give a comfortable impression through the visuals displayed. In assessing visual comfort, there are several aspects that need to be considered, namely layout, light intensity, audience viewing angle, and colour. This research uses qualitative and quantitative methods. This research starts from making observations at the research location, after making observations then identifying data validation based on SNI in sports buildings. The observation results show that there are still several aspects that are not in accordance with the SNI that has been determined. PT Arun GOR still has shortcomings in terms of lighting and user facilities so that it can affect user visual comfort.

Keywords: Sports hall, visual comfort, SNI